


PRIOR ART

FIG. 1








FIG. 3



ナジリ



いう <u>シ</u> エ






FIG. 6



Dashboard is updated automatically. Factory is notified with the new

relay manufacturing capability and quality data to a database so that engineers can oplimize using the Sensors in the floor continuously most recent capability.



Outsourcing

lamp part on the html file

shown on the web

browser

Lamp Engineer Double Click on the

aiready automatically updated on the Fan engineer can access the lamp subsystem to get the newest lamp brightness metric (which was system)

submitted by autsourding using the Fan engineer can run lhe model DFSS analysis integration tool.

	题		
Section Control of Con	Outpureparam 1.68 fur.	Outputz	Total Load
Fabrica and Property of the Party of the Par	Creek Langth Walarist 311/finess	PK	
			•

203 Cannot double click or access any other part of the system. Submit metrics of the new materials and their quality. Submit the new transfer the fan subsystem html file shown on the web Transfer function part of Double Click on the function. browser

B

ā

Submit the new model, its wrapper, its location on the network. Submit

the modified value of lamp

brightness.

System automatically checks for

authorization.

site past best models and associated hints.

Lamp Engineer can get at the same

Top Level Process: A




FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14




FIG. 15